ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mananagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| DASARAHALLI | 15 | T Dasarahalli |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0188, W0221, W0167, W0183, W0179, W0171 | NA | Grape Garden |
| **Segment No.** | **Total Length (m)** | |
| 15/C-W0188/S032304 | 380.25 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 359.34 | 77.520607 | 13.043507 | 77.517368 | 13.044178 | S M Road | Dead End |
| 2 | 20.91 | 77.517936 | 13.043978 | 77.517920 | 13.043790 | Grape Garden Main road | Dead End |

### Work Details

History of Road / Lane / Circles

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Construction of Rcc drains and Improvements to roads at Grape Garden Main road in Dasarahalli Wa | 5000000 | 2017-18 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2017 - 2018 | Drain Maintenance | |
| Tender | **Work Details** | **Job No. / Work Code** |
| Tender | | 015-18-000001 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/DD/WO/183/2017-18 | 10/01/2018 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 10/01/2018 | 09/04/2018 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| KRIDL | | 4994115.00 |
| **Phone No.** | **E-Mail ID** | |
| 9591836710 | | |

Zone: DASARAHALLI Ward No: 15 Ward Name: ದಾಸರಹಳ್ಳಿ Street ID: W0188, W0221, W0167, W0183,

ಟಿ.ದಾಸರಹಳ್ಳಿ ವಾರ್ಡ್-ಎಂಥಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಡಿಂಬಿ
ಬೆಂಗಳೂರು